



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

| General           |            |                   |           |                      |                |          |
|-------------------|------------|-------------------|-----------|----------------------|----------------|----------|
| Zone              |            | Ward No.          |           | Ward Name            |                |          |
| YELAHANKA         |            | 7                 |           | Byatarayanapura      |                |          |
| Street ID         |            | Street Name       |           | Significant Landmark |                |          |
| W0618, W0797      |            | NA                |           | Amruthnagar          |                |          |
| Segment No.       |            | Total Length (m)  |           |                      |                |          |
| 7/C-W0618/S031716 |            | 128.16            |           |                      |                |          |
| Segment Details   |            |                   |           |                      |                |          |
| Seg No.           | Length (m) | Start Coordinates |           | End Coordinates      |                | To       |
| 1                 | 128.16     | 77.596620         | 13.056811 | 77.597742            | 13.056445      | Dead End |
|                   |            |                   |           | From                 | 4th Cross Road |          |

| Work Details                                                                                                                     |                                                              |                                                          |  |
|----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|----------------------------------------------------------|--|
| History of Road / Lane / Circles                                                                                                 |                                                              |                                                          |  |
| Name of the Work                                                                                                                 |                                                              | Sanctioned Estimated Amount (Rs.)                        |  |
| Improvements to drains of 5th cross road of pampa extension to 13th cross road of pampa extension in ward no.07, Byatarayanapura |                                                              | 9990000                                                  |  |
| Sanctioned Year                                                                                                                  |                                                              | 2019-20                                                  |  |
| Year                                                                                                                             | Type of Work                                                 | Other Work Type                                          |  |
| 2019 - 2020                                                                                                                      | Drain Maintenance                                            |                                                          |  |
| Tender                                                                                                                           | Work Details                                                 | Job No. / Work Code                                      |  |
| Tender                                                                                                                           | 1.Construction of Drains.2.Providing and fixing Kerb Stones. | 007-19-000017                                            |  |
| Work Order No.                                                                                                                   | Work Order Date                                              | Period of Extention                                      |  |
| BBMP/EE/BTP/WO/236/19-20                                                                                                         | 17/03/2020                                                   |                                                          |  |
| Defect Liability Period From                                                                                                     | Defect Liability Period To                                   | Multiple road involved with the same Job No/ Work Code # |  |
| 02/09/2020                                                                                                                       | 01/09/2023                                                   | Yes                                                      |  |

| Contractor Details |                              |                                    |
|--------------------|------------------------------|------------------------------------|
| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
| U.Ramesh           |                              | 0.00                               |
| Phone No.          | E-Mail ID                    |                                    |
| 7846844447         |                              |                                    |

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W0618, W0797

Date: 04/11/2020

Time: 13:49:31

RH 20201104134931

Page 1 of 2

  
Assistant Executive Engineer  
Kodigehalli Sub Division  
Bruhat Bangalore Mahanagara Palike  
Bangalore - 560 092

# Field Inspection Details

Number of Trees

0

Any Other Information

Name

Pushpalatha.N.D

Date of Inspection

03/11/2020

Remarks

Category

Image

Photo Remark

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

## Remarks

| Designation | Approver Name       | Date       | Target Date | Remark                   |
|-------------|---------------------|------------|-------------|--------------------------|
| CE          | Sri.S.P.Ranganath   | 04/11/2020 | 04/12/2020  | As proposed              |
| SE          | Vijay Kumar Haridas | 04/11/2020 | 02/12/2020  | Forwarded                |
| EE          | Mohandas H.T        | 03/11/2020 | 02/12/2020  | Verified                 |
| AEE         | G.Srinivasa Murthy  | 03/11/2020 | 02/12/2020  | Verified                 |
| AE          | Pushpalatha.N.D     | 03/11/2020 | 02/12/2020  | Mobile Verification Done |
| AE          | Pushpalatha.N.D     | 03/11/2020 | 02/10/2020  | Forwarded                |

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W0618,  
W0797

Date: 04/11/2020

Time: 13:49:31

RH20201104134931

Page 2 of 2

*Pushpalatha.N.D*  
*AE (202)*

*C/S*  
Assistant Executive Engineer  
Kodigehalli Sub Division  
Bruhat Bangalore Mahanagara Palike  
Bangalore - 560 092



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

| General                              |            |                   |           |                      |           |                           |          |
|--------------------------------------|------------|-------------------|-----------|----------------------|-----------|---------------------------|----------|
| Zone                                 |            | Ward No.          |           | Ward Name            |           |                           |          |
| YELAHANKA                            |            | 7                 |           | Byatarayanapura      |           |                           |          |
| Street ID                            |            | Street Name       |           | Significant Landmark |           |                           |          |
| W0718, W0819, W0658,<br>W0817, W0648 |            | NA                |           | Pampa Extension      |           |                           |          |
| Segment No.                          |            | Total Length (m)  |           |                      |           |                           |          |
| 7/C-W0718/S030905                    |            | 439.95            |           |                      |           |                           |          |
| Segment Details                      |            |                   |           |                      |           |                           |          |
| Seg No.                              | Length (m) | Start Coordinates |           | End Coordinates      |           | From                      | To       |
| 1                                    | 129.70     | 77.598557         | 13.052988 | 77.598278            | 13.051849 | Pampa Extension Main Road | Dead End |
| 2                                    | 242.71     | 77.598906         | 13.053318 | 77.598337            | 13.051196 | 3rd Main Road             | Dead End |
| 3                                    | 67.54      | 77.597736         | 13.051489 | 77.598348            | 13.051374 | 2nd Main Road             | Dead End |

| Work Details                                                                                                                     |                                                                                                                     |                                                          |
|----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| History of Road / Lane / Circles                                                                                                 |                                                                                                                     |                                                          |
| Name of the Work                                                                                                                 | Sanctioned Estimated Amount (Rs.)                                                                                   | Sanctioned Year                                          |
| Improvements to drains of 5th cross road of pampa extension to 13th cross road of pampa extension in ward no.07, Byatarayanapura | 9990000                                                                                                             | 2019-20                                                  |
| Year                                                                                                                             | Type of Work                                                                                                        | Other Work Type                                          |
| 2019 - 2020                                                                                                                      | Drain Maintenance                                                                                                   |                                                          |
| Tender                                                                                                                           | Work Details                                                                                                        | Job No. / Work Code                                      |
| Tender                                                                                                                           | 1.Construction of drains and culverts.2.Providing and laying RCC Covering Slabs.3.Providing and fixing Kerb Stones. | 007-19-000017                                            |
| Work Order No.                                                                                                                   | Work Order Date                                                                                                     | Period of Extension                                      |
| BBMP/EE/BTP/WO/236/19-20                                                                                                         | 17/03/2020                                                                                                          |                                                          |
| Defect Liability Period From                                                                                                     | Defect Liability Period To                                                                                          | Multiple road involved with the same Job No/ Work Code # |
| 02/09/2020                                                                                                                       | 01/09/2023                                                                                                          | Yes                                                      |

| Contractor Details |                              |                                    |
|--------------------|------------------------------|------------------------------------|
| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
| U.Ramesh           |                              | 0.00                               |
| Phone No.          | E-Mail ID                    |                                    |

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W0718,  
W0819,  
W0658,  
W0817,  
W0648

Assistant Executive Engineer  
Kodigehalli Sub Division  
Bruhat Bangalore Mahanagara Palike  
Bangalore - 560 092

## Field Inspection Details

Number of Trees

Any Other Information

Name

0

Pushpalatha.N.D

Date of Inspection

Remarks

03/11/2020

Category

Image

Photo Remark

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Remarks

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W0718,  
W0819,  
W0658,  
W0817,  
W0818

*CyD*  
 Assistant Executive Engineer  
 Kodigehalli Sub Division  
 Bruhat Bangalore Mahanagara Palike  
 Bangalore - 560 092

| ation | Approver Name       | Date       | Target Date | Remark                   |
|-------|---------------------|------------|-------------|--------------------------|
|       | Sri.S.P.Ranganath   | 04/11/2020 | 02/12/2020  | As proposed              |
|       | Vijay Kumar Haridas | 04/11/2020 | 02/12/2020  | Forwarded                |
| EE    | Mohandas H.T        | 03/11/2020 | 02/12/2020  | Verified                 |
| AEE   | G.Srinivasa Murthy  | 03/11/2020 | 02/12/2020  | Verified                 |
| AE    | Pushpalatha.N.D     | 03/11/2020 | 02/12/2020  | Mobile Verification Done |
| AE    | Pushpalatha.N.D     | 03/11/2020 | 02/10/2020  | Forwarded                |

*Pushpalatha.N.D*  
*De (a)*

*Cy*  
Assistant Executive Engineer  
Kodigehalli Sub Division  
Bruhat Bangalore Mahanagara Palike  
Bangalore - 560 092

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W0718,  
W0819,  
W0658,  
W0817,  
W0818